

## GOVERNMENT OF KARNATAKA mataka State Fire and Emergency Services HUBBALLI-580025.

Date: 25-09-2024

## C.NO:31/ADV/DFO/AMR-HUBLI/2024.

To,
The Chairman,
Vishwachetan Foundation's,
Group of Institutions,
Sy no 22/2B, Gayatri Nagar,
Sharewad Road, Pale village.
Hubballi-580 028.

Sir,

Sub: Issue of Revised '*Fire safety recommendation/Advice'* to Vishwachetan Foundation's, Group of Institutions, Sy no 22/2B, Gayatri Nagar, Sharewad road, Pale village, Hubballi-580 028, Dharwad District.

Ref: 1) Request Letter Dated: 19-09-2024.

2) No.GBC (2)044/2020-21 dated 21/06/2022 S.O No.156-B.



With reference to the subject above cited, the premises of "<u>Vishwachetan Foundation's, Group of Institutions</u>" building consisting with Lower Ground + Ground floors situated at Servey no 22/2B, Gyatri Nagar, Sharewad road, Pale village, Tq: Hubballi, Dharwad Dist-580 028. Inspected by me on 24/09/2024 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under.

## ANNEXURE-1 (Up to 14.99 mtrs. in height)

Group B Education Building

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings sub division B1& B2. (These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory)

## A. Details of the building / premises :-

1.	Name and Address of the Applicant.	:	Chairman, Vishwachetan Foundation's, Group of Institutions, Sy no 22/2B, Gayatri Nagar, Sharewad road, Pale village, Tq: Hubballi. Dist: Dharwad. Pin: 580 028.
2.	Name and Address of the premises.		Vishwachetan Foundation's, Group of Institutions, Sy no 22/2B, Gayatri Nagar, Sharewad road, Pale village, Tq: Hubballi. Dist: Dharwad. Pin: 580 028.

Page | 1

3	B. Name and Address of		Vishwachetan Foundation		
Office	the building owner.		Vishwachetan Foundation's, Group of Institutions,		
205	no 13 los o 13 em los mannes y 15.		SV no 22/2B Cayatri M		
4.50			Sy no 22/2B, Gayatri Nagar, Sharewad road, Pale village, Tq: Hubballi.		
	ALL THE RESERVE AND ADDRESS OF THE PERSON OF		Dist: Dharwad.		
			Pin: 580 028.		
4	. Number of buildings		: Only one building.		
5.	5 Number of fl				
6.	0.				
	Floor-wise details of occupancy:-				
	Lower Ground floor	:	Class rooms-03, Toilet-1, Canteen-1, Laboratary-6 Store room-2, HOD room-1, Power room-1.		
			Class rooms 12 Library		
	DENET OF STREET		Class rooms-12, Library-1, staff room-1, Ladie		
	Ground floor	1:			
	Date (That have been 1820)	10			
			Principal room-1, Strong room-1, waiting hall-1		
7.	Height of the building	23.1	08.30 mtrs		
8.	Site area	1:	5 Acre		
9.	Built-up area of each floor:-	odi	by to the state of		
	Lower Ground floor		1228 47 ag matus		
	Ground floor		1228.47 sq.mtrs		
10.	Total built-up area		2498.63 sq.mtrs		
11.	Surrounding properties: 3727.10 sq.mtrs				
	West(F)		Agriculture land		
	North(S)		Agriculture land		
1,00	0 11 15		09.00 mtr wide road. Agriculture land		
12.	Set-back area available a	rou	Ind the building		
	Set-back area available around the building :  East(R) : 20.00 mtrs				
West(F) : North(S) :					
			20.00 mtrs 25.00 mtrs		
	South(S)	(	00 00 mtrs		
Allo	wed setback (open space)	sh	ould be maintained free from further obstruction		
		~ J	naintain setbacks as per Local ZP		

Note: Recommended to provide and maintain setbacks as per Local ZR.

B. on inspection of this Educational premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view.

5.No (1)	Details (02)	Existing (03)		Recommendations (04 )	
1. Acc	Accessibility to the premises is side of the premises hardened to carr 45,000 Kg's.		abutting 09.00 road on northern ses. The road is	Adequate	
10 m	No. of Provided 02 en entrances mtrs width of gat mtrs wide public side of the premis		e from the 09.00 road on northern	Adequate	
3. Ge			no. Of Diesel KVA capacity.	Adequate	
4.		Staircases	01	Recommended to provide	
Vision		Staircases	2.40 mtrs	another one staircas	
Φ			22.02 cms	maintaining travel distance wit	
as	Width Of			22.50 mtrs. With minimum 02.0	
airo	Width Of Treads Height Of Risers Nos. Of Riser Per Flight		15.24 cms	mtrs width, 20 mm threads width	
Sta			11 nos	15 mm threads height, 01	
belonne	Height O	f Handrails	0.6 mtrs	mtrs handrail, with minimur	
a 900,80	Head Room Clearance		3.20 mts	02.20 head room clearance.	
				each staircase landing.  2) One mechanic foar extinguisher of 9 ltrs capacity one ABC type extinguisher of kgs capacity should be provided near diesel generator.  3) 01 No CO <sub>2</sub> fire extinguisher of the staircast of the stairca	

12

Daga I 2

6.	Hose reel hose system	Not Provided	Recommended to provide 02 no's of Hose reel hose system near the stair case (one hose reel hose system for every 1000 sq.mtrs) the hose reel hose Is of minimum 19 mm dia and of 30 mtr length shall be provided to reach the farthest point of each floor and shut off branch having a nozzle of 5 mm size. The hose reel hose should be connected at each landing.
7.	At the terrace tank level with minimum pressure of 3.5 kg/cm2.		The system should be connected to an booster pump of 450 LPM of of additional 5 HP capacity.  Further the system should be connected to an alternative source of power supply.
8.	Terrace tank	Provided 02 no. Of syntax tank capacity of each 1000 ltr 2000 ltr capacity in terrace.	The system should be connected to an over head tank of 5,000 ltr capacity and further if basement is provided the tank capacity shall be increased to 10,000 ltrs capacity.  (The water tank should be kept exclusively fire fight purpose)  Note: If the existing building is not capable of sustaining the weight of 5000/10000 ltrs tank capacity provision shall be made to provide water tank on the side of the building with support from ground level by providing RCC column structure or MS column structure.  If there is no option to provide even the above mentioned overhead tank provision shall be made to provide underground water tank of capacity with submersible pump of 5-7 HP capacity.
901 911 9 55 11	phosp must pritor made two strieth bas by		

and the second

The state of the s			
9.	Escape routes	Not Marked	Recommended to provide Direction in which the inmates should have to move in the event of an emergency have to be indicated in the corridor / passage as a guide during evacuation. These shall be marked with luminous / auto glow paint directing to the occupants towards the emergency exits.
10.	Fire order (Fire safety plans)	Displayed	Instructed them to display notice board written in bold letters indicating the action to be taken by the Occupants in case of any emergency should be displayed along with the Telephone number of Hubballi city fire station i.e. 0836-2240789 and 101,112, 080-22971550, 22971500, 22971600 and the telephone number of nearest ambulance service and Police Station.
11.	No Smoking Board	Displayed	Complied.
12.	Fire Siren	Not installed	A Fire siren shall be installed in the premises to inform the inmates/students in case of a fire emergency and evacuate the area.
13.	Nominate One fire nodal officer	Not Appointed	A fire nodal officer Should be nominated either from teaching or non-teaching staff.
14.	Fire fighting training	Not Imparted	At-least 40% of Teaching and non Teaching staff should be trained in basic fire fighting at R.A.Mundkur Fire and Emergency Services Academy, Bannerghatta Road, Bangalore-29 or Regional Training Centre.

Fire precautionary measures:

A. Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.

B. Accumulation of combustible waste in and around the premises should be avoided.

- C. The exit ways shall be always kept clear without any obstruction.
- D. Liquefied petroleum gas should not be stored in the building.
- E. The doors shall not be kept locked / latched during working hours and shall be free from obstruction.
- F. During the class hours the class room doors shall not be locked from inside to outside.

As per Honorable Supreme Court order all teachers and staffs shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14<sup>th</sup> of every year by conducting Fire Safety drills with co-ordinate with fire service department.

Under the above circumstance the Karnataka Fire and Emergency Service Department is issuing of Revised Fire Safety Recommendation to "Vishwachetan Foundation's, Group on Institutions" situated at Servey no 22/2B, Gayatri Nagar, Sharewad road, Pale village, Tq: Hubballi, Dharwad Dist-580 028. Subject to condition and compliance of the above recommendations in column 4 of serial B within 03 months compliance to the undersigned.

\*All requirements recommended above are as per National Building Code-2016 Part-4 clause 3.1.4 of Fire and Life safety will have to be complied with mandatorily.

From the above details it is clear that the 'Management' of the above Educational building have been recommended to provide fire precautionary measures as per National Building Code 2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2. After full-filling the above recommendations, a Certificate should be obtained by this office. If at any time any of the conditions are found not complied with, this Certificate shall stand withdrawn/cancelled.

The Revised <u>Fire Safety Recommendation</u> is valid for a period of **one year** from the date of issue and it is not renewable.

Yours faithfully

Karnataka State Fire and Emergency Services Fire Station, HUBBALLI-25.